

VEHICLE INSPECTION REPORT

PE63MZY

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/10/2013

VIN XLRAE45FF0L432005

Axle Combi 4x2

Year 2013

Body Style Box Van

Rear Suspension Steel

Mileage 858,521 Km Warranted

MOT Due 30/11/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

WARNING LIGHT ON DASH

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4


OSO1






OSO2

OSO3


OSO4

Photos





Condition Check



Damage Photos



1: Wing of
Cracked
Replace

2: Fog Lamp Surround of
Broken
Replace



3: Bumper Front
Dented
With Paint Damage

4: Screen Front
Chipped
Over 10mm



5: Bonnet
Chipped
Multiple Chips

6: Wing nsf
Poor Previous Repair
Poor Paint



7: Other
N/A
N/A

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Other
N/A
N/A

10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Other
N/A
N/A

12: Other
N/A
N/A



13: Door osf
Chipped
Edge Chip

14: Door osf
Scratched
Over 25mm Thru Paint



15: Door osf
 Scratched
 Over 25mm Not Thru Paint

16: Door Mirror Assy osf
 Scuffed (Unpainted)
 Over 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	Fault	
ABS light illuminated	OK		Service indicator light illuminated	OK	