

VEHICLE INSPECTION REPORT

YR68TGX

Ford Transit Custom 300 2.0 TDCI 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/09/2018

Year 2018

Mileage 97,123 Miles
Warranted

Fuel Type Diesel

GVW 3000kg

Colour WHITE

VIN WF0YXXTTGYJL84976

Body Style Panel Van L2

MOT Due 21/07/2026

CAP Clean £6,225.00

CAP Average £5,275.00

CAP Below £4,025.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOADING DOOR

Tyres

NSF

NSR

OSF



OSR


Spare

Features


- Park assist camera
- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos




1: Screen Front
Cracked
Replace

2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

4: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



5: Qtr Panel osr
Scratched
UpTo 25mm Not Thru Paint

6: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	